

# Terminal 91 Northwest Fender Replacement


Kenneth Lyles – Director, Fishing and Commercial Operations

Mark Longridge – Capital Project Manager


# Project Location



# Current Condition



- 70% of piles show deterioration
- 30% of piles currently broken, split or hollowed



# Proposed Replacement

